


The Fazilka Co-op. Sugar Mills. Ltd., Fazilka


NIT FOR RE-CONDITIONING OF ROTORY VACUUM FILTER(8'x16') FOR THE SEASON 2021-22


Sr.No	Description of job/item	Rate quoted.
1.	<u>Reconditioning of Vacuum Filter</u>	
	1 Dismantling & refitting of worn out SS Screens 50-Nos approximate .	Lump sum rate /screen
	2 Replacement of junction box with capillary	Lump sum rate /Piece
	3 Hydraulic testing of vacuum filter. checking of internal junction box and capillary tubes	Lump sum rate per RVF
	4 Dismantling and refitting of SS decking plate(as required)	Lump sum rate /Piece
	5 Dismantling and refitting of divisional strips.	Lump sum rate /piece
	6 Repair of high flow GM valve.	Lump sum rate /Piece
	Note: No. of worn out screens may increase or decrease at the time of executing the jobs.	


Terms & Conditions

- 1- All materials will be supplied by the mills.
- 2- GST: Extra if applicable.
- 3- Payment: payment terms will be decided at the time of negotiation.
- 4- Any dispute Subject to Fazilka Jurisdictions only.
- 5- Contractor will have to complete the repair job within stipulated time. Mill Management reserve the right to get the work done by any other contractor at your risk and cost if the work is delayed


A.E(M)


M.C


CHIEF CHEMIST


GENERAL MANAGER